## Town of Kennebunkport - KMBS FLEET REPORT FY22

				# Service	Average Volume Between	Avg Response			Projected Monthly		Actual Monthly	Actual Monthly			
Location	Make/Model	Serial Number	Vendor ID	Calls	Calls	Time	Down Time	Uptime%	Volume Black	Volume Color	Volume Black	Volume Color	Model Intro Date	Model Age (years)	Model Type
Kennebunkport Fire Department															
Main Office	Konica Minolta BH4422	AAFM011000329	9499-5961	0	0	0.0	0.00	100.00%	234	0	234	0	8/1/18	4.08	Black Laser MFP
Kennebunkport Highway															
Main Office	Konica Minolta BH4422	AAFM011001137	9499-5959	1	0	0.0	0.00	100.00%	18	0	78	0	8/1/18	4.08	Black Laser MFP
Kennebunkport Parks and Rec															
Main Office	Konica Minolta BH4422	AAFM011001133	9499-5960	0	0	0.0	0.00	100.00%	83	0	1,000	0	8/1/18	4.08	Black Laser MFP
Kennebunkport Police															
Main Office	Konica Minolta BH658	AA6R011003202	9494-4450	3	0	0.8	4.79	99.79%	4,394	0	2,269	0	5/1/17	5.33	Black Photocopier
Kennebunkport Public Health															
Public Health	Konica Minolta BH4422	AAFM011001139	9499-5962	1	0	0.0	0.00	100.00%	488	0	747	0	8/1/18	4.08	Black Laser MFP
Kennebunnkport Sewer															
Main Office	Konica Minolta BH308	AA6W017003565		4	9,682	0.31	2.16	99.91%	761	0	664	0	6/1/16	6.25	Black Photocopier
Kennebunkport Town Hall															
Code Enforcement	Konica Minolta BHC458	A79M011044606	9494-4449	3	71,788	0.0	0.00	100.00%	1,925	2,242	1,743	2,569	8/1/16	6.08	Color Photocopier
Office	Konica Minolta BHC658	A79J013007406	8802-1930	10	19,751	2.8	28.99	98.76%	8,836	833	6,631	2,203	5/1/17	5.33	Color Photocopier
TOTALS & AVERAGES				22	33,740	3.90	35.93	99.81%	2,092	1,538	1,671	2,386		4.91	

Equipment with 5 or more calls for the reporting period July 1, 2021 to June 30, 2022											
Current Equipment	Location	Serial Number	# Service Calls	Current Total Meter	Avg Copies between all Service Calls (incl PM)	Avg Response Time	Down Time (brs)	Uptime%	Avg Monthly Volume Total	Model Type	Reasons for service calls
Kennebunkport Town Hall Office	Konica Minolta BHC658	A79J013007406	10	405,318	19,751	2.8	28.99	98.76%	8,834	Color Photocopier	1 service call on this copier was for poor quality; technician replaced the black drum. Another call was for noise in the fusing unit, which was resolved with lubrication. However, the remaining 8 calls were for jamming in the finisher, fusing unit, and doc feeder. These calls are being addressed with the vendor because the last service call in May resulted in the replacement of a number of major parts. This machine has been escalated to the vendor for immediate resolution.